



## **WABCO - 12999797 - Kit de reparación de indicador de desgaste PAN 22 VALX**

DAF 877936

DAF 0877936

KÖGEL 6500565

LECITRAILER 4091029

LIEBHERR 10326499

SAF 3424200900

SCANIA 2091389

SCHWARZMÜLLER 79857

Schmitz 1104516

Schmitz 1067145

Schmitz SCB1067145

VALX 50380002

VOLVO WA12999797